

Work Order ID 60319

Page 1

Monday, July 12, 2010 7:56:08 AM

Item ID: D4010-1

Accept



Setup Start



Revision ID:

Stop



Item Name: Bearpaw

Start Date: 7/2/2010 Start Qty: 6.00



Cust Item ID:

Required Date: 7/9/2010 Req'd Qty: 6.00



Customer:

Reference: Return 2010 / RA110034 / NCR10-020

Run Start



Approvals: Process Plan: _____

Date: _____ Tooling: _____ Date: _____

Stop

QC: *[Signature]*Date: 100712 SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D4010	D

100



QC

Memo

0.00

0.00

Quality Control

Original B53816 qty 3 & B53817 qty 3.

110



QC21- Final Inspection - Work Order Release

0.00

QC

Memo

0.00

Quality Control

Items are scrap & placed in the eng lab mezzanine for engineering reference & use only.
Identify with the RA #.

→ S1007109

was put up in eng.

[Signature]

Bl0-7-12